



RTS

Report Date: 25/02/2026 09:31:46 am

Reference

Part

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 20870K9530NK
FLD04 1
FLD05 CLAMP
FLD08 25/02/2026 09:31



CR00284638246

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 20870K9540NK
FLD04 1
FLD05 CLAMP
FLD08 25/02/2026 09:31



CR00284638247

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A543K1270
FLD04 1
FLD05 ARM REST (R.H)
FLD08 25/02/2026 09:31



CR00284638248



Report Date: 25/02/2026 09:31:46 am

Reference Part

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A543K1280
FLD04 1
FLD05 ARM REST (L.H)
FLD08 25/02/2026 09:31



Ref. CR00284638249

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A543K2741
FLD04 1
FLD05 BRACKET (R.H)
FLD08 25/02/2026 09:31



Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A543K2751
FLD04 1
FLD05 BRACKET (L.H)
FLD08 25/02/2026 09:31





Report Date: 25/02/2026 09:31:46 am

Reference Part

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A553K2341
FLD04 1
FLD05 LEVER (L.H)
FLD08 25/02/2026 09:31



CR00284638252

Report

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A553K2351
FLD04 1
FLD05 LEVER (R.H)
FLD08 25/02/2026 09:31



CR00284638253

Ref. CR0028463
Model PC360NLC
Loc. 636W
FLD10 K75967
Part 2A770K5691
FLD04 1
FLD05 BLOCK
FLD08 25/02/2026 09:31



CR00284638254



RTS

Report Date: 25/02/2026 09:31:46 am

Reference

Part

Repor